# UNCLASSIFIED

AD 292 075

Reproduced by the


ARMED SERVICES TECHNICAL INFORMATION AGENCY
ARLINGTON HALL STATION
ARLINGTON 12, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

292 075



Monthly Progress Report

P-B1980-2

HERO SUPPORTING STUDIES

bу

Norman P. Faunce Paul F. Mohrbach

August 1 to August 31, 1962

Prepared for

U.S. NAVAL WEAPONS LABORATORY
Dahlgren, Virginia
Code WHR

Contract No. N178-8102

\$2.60

CV

# THE FRANKLIN INSTITUTE

LABORATORIES FOR RESEARCH AND DEVELOPMENT PHILADELPHIA PENNSYLVANIA

Monthly Progress Report

P-B1980-2

HERO SUPPORTING STUDIES

bу

Norman P. Faunce Paul F. Mohrbach

August 31, 1962

Prepared for

U.S. NAVAL WEAPONS LABORATORY
Dahlgren, Virginia
Code: WHR

Contract No. N178-8102

P-B1980-2

#### ABSTRACT

A program of evaluation tests intended to extensively characterize hot wire-bridged EED been outlined. This schedule includes tests for both dc and RF functioning sensitivity. Tests to determine the rate of change of resistance with temperature, the RF cook-off power, and the effect of low level dc or RF excitation on normal functioning responses round out the program. The modified resistance ignition element is to be the first component to be tested by this plan.

Analyses are being made of errors to be expected in RF power measuring systems. The directivity errors associated with use of directional couplers to measure incident and reflected power are developed. These errors, both of which approach a common value of 2% for couplers with 40 db of directivity combine to give a possible maximum error approaching infinity.

P-B1980-2

#### SUMMARY

The component testing phase of the HERO Supporting Studies has been critically reviewed and a test schedule for hot-wire-bridged EED's has at last emerged. Reworking a die compression pin has been done on the component development phase. Major emphasis has centered on evaluating sources of error in power measuring systems, notably that from use of directional couplers. Continued effort to fabricate the stub tuner precision guides accounts for most of the physcial labor during this period.

At a meeting with NWL representatives on the last working day of this period, we agreed upon a test outline for hot-wire-bridged EED's. This schedule was prepared by NWL using as a guide our proposed plans of the previous month. A few minor amendments were made at this meeting; the final draft is acceptable to all concerned. In addition a schedule was outlined for tests to be performed upon the MK 7 MOD 0 protected ignition element. This evaluation schedule is brief, because a number of the "General Test Program" tests have already been performed. Receipt of the lot of 800 MK 7 MOD 0 elements are expected early in the coming month, and we will begin to schedule them for tests soon thereafter.

A differential method for measuring RF power has been studied. In concept it appears to be ideally suited to measuring input to an EED. Examination of the probable sources of error has shown the need to be suspicious of the result when the power measured even by highly accurate directional couplers is combined to determine net power. For example, measurement of the power to a 2-ohm resistive load terminating a 50-ohm line may be in error by as much as 35%, even though the incident and reflected power errors are each only about 2%. This error may increase for loads having a higher reflection coefficient. These values represent possible error brought about by a unique phase relationship between measured voltages. Means for limiting actual error to a value considerably less than this should be possible. This will be our objective during the coming weeks, when we will continue our investigation of this method both theoretically and empirically.

The tuning assemblies for the new attenuation measuring system should be completely assembled and checked out during the coming month. This will conclude work in this direction except, possibly, extending the new technique to measurements at lower frequencies. Some thought has been given to such an extension, and should results obtained with the system warrant it, we may proceed accordingly.

P-B1980-2

# TABLE OF CONTENTS

			Page
	ABST	RACT	i
	SUMM	ARY	ii
1.	COMP	ONENT TESTING	1
	1.1	Outline of HERO Testing Program for all Hot-W re- Bridged EED's	1
	1.2	Outline of HERO Tests for the Modified MK 7 Ignition	_
		Element	5
2.	COMP	ONENT DEVELOPMENT	7
3.	INST	RUMENTATION	7
		Improved RF Attenuation Measuring Systems	7 7
		3.2.1 Incident Power Error	8 13 14
	ACKN	OWLEDGEMENTS	16
		LIST OF TABLES	
			Page
Tab	<u>le No</u>	•	
1	-1	General Test Program	2
1	-2	Test Program for the Modified MK 7 Ignition	,
		Element	6
		LIST OF FIGURES	
			Page
			TORC
	ure N	<del></del>	_
_	-1	Power Measurement with Directional Couplers	9
3	-2	Maximum Measurement Error Due to Directional Coupler Directivity	13

P-B1980-2

#### 1. COMPONENT TESTING

At the conclusion of the previous reporting period The Franklin Institute had submitted their recommended procedure for evaluating wire-bridge electro-explosive devices. This took the form of three test schedules differing in the detail of the data that would be produced by each. Correspondingly they each differed in the degree to which they would allow the items under test to be classified according to their RF (and dc) characteristics.

During the present period, we have done little more on this phase of study except to review our proposal, thereby confirming our belief that it represents a sound approach. Personnel at the Naval Weapons Laboratory have been similarly engaged, in the expectation of preparing a single unified test schedule. Agreement on a general program was reached near the end of the month, and a detailed schedule of tests was prepared for evaluation of the MK 7 MOD 0 RF attenuated ignition element in this manner.

# 1.1 Outline of HERO Testing Program for All Hot-Wire Bridged EED's

The general test program for conventional wire-bridged EEDS is given in Table 1-1. A rather extensive evaluation is suggested by this schedule which calls for the expenditure of nearly one thousand ignition elements. If it were necessary to reduce this number, it would be readily possible to modify the general outline with a corresponding loss in detail of evaluation results.

P-B1980-2

# Table 1-1

# GENERAL TEST PROGRAM

	De	scription of Test	Maximum Number of Items
I.	DC	Sensitivity	
	1.	Establish current vs. time-sensitivity curve if unknown by firing 0.1 msec. or less, 1.0 msec, 10 sec.	200
	2.	Determine the alteration in sensitivity resulting from exposure to (say) .1% firing current for five minutes.	100
	3.	Determine the change of resistance with respect to time (dr/dt) for three dc pulse widths (0.1 msec or less, 1.0 msec, 10 sec).	<u>30</u> 330
II.	नन	Sensitivity	<i>33</i> 2
		•	
	1.	Establish RF sensitivity under CW conditions at five frequencies (suggest 5, 30, 250, 1000, 5000 Mc).	250
	2.	Calculate RF sensitivity under pulsed conditions from dc data and check by firing at 2 pulse lengths and repetition rates.	100
	3.	Check RF sensitivity as in II.1 above with instrumented units.	10
	4.	Lead-to-case RF test where applicable.	50
	5.	Expose 50 items each to 0.1% level CW and 0.1% level pulsed RF, 1 $\mu$ sec pulse length, for 5 minutes each at selected frequency. Fire subsequently in dc Bruceton to check dudding and alteration of sensitivity.	<u>100</u> 510

P-B1980-2

# III. Cookoff Sensitivity (For attenuated items use 3 kMc Frequency), CW Modulation

#### 1. Lead-to-Case, air environment

a.	. EED only - no heat sink.				
b.	EED in heat sink (heat sink to be				
	agreed upon later).	25			

#### 2. Lead-to-Lead

a. EED only - no heat sink b. EED in heat sink (heat sink to be	25
agreed upon later).	<u>25</u>
	<u>100</u> 940 Total

On the other hand, this program contains tests which may be found unnecessary provided some correlation is shown between similar phenomena. For example, Tests I-2 and II-5 are intended to show the same effect; if low level dc alters the item's sensitivity, we would expect a comparable low level RF to have the same effect. When this has been demonstrated with reasonable clarity we shall omit test II-5.

A few comments regarding the tests outlined in the table seem to be in order.

The first test (I-1) is a standard constant current evaluation. From this we learn the magnitude of current necessary to be delivered to the item undergoing test for various time intervals so as to result in a 50% probability of fire. Current pulse durations from micro-seconds to minutes may be used depending upon the nature of the item. In any event the pulse durations used for tests should include one specified by design or ordinary use, a time interval relatively short by comparison, and one correspondingly longer.

P-B1980-2

In some cases if the EED is normally fired from a charged capacitor it may prove desirable to perform a capacitor discharge sensitivity test at several capacitances.

Test I-2 has been discussed previously; this test shows degradation wrought by low level excitations.

The final dc test (dr/dt evaluation) provides the link between RF and dc firing test results. Since power is used for describing RF response we must convert dc firing current to dc firing power. Knowledge of dr/dt is necessary for this conversion.

RF sensitivity is determined both for CW and pulsed excitation (Tests II-1&2). We believe that CW RF functioning levels are readily determined from dc long pulse time functioning levels; the difference being attributable to a frequency-dependent loss. Similarly, short time dc pulse firing response should be indicative of pulsed RF response. Prediction of pulsed RF levels from comparable dc levels has been made a part of this program to verify this conjecture.

For many components submitted for evaluation, the available quantity may be limited. In Test II-3, therefore, we have to learn, by expending only 10 units, as much as possible to indicate the results that would be derived from expending 930 units. A number of non-destructive tests will be evaluated to provide clues to a reasonable estimate of the results that might be obtained from a more extensive testing program. We will be fortunate in having results of the extension evaluation on hand to verify or refute our predictions based on this exceedingly small sample.

Test II-4 is included to investigate the possibility of leakage currents from bridge posts to case being responsible for initiations.

P-B1 980-2

An additional RF test is included to study the probability of low level RF excitation altering the normal functioning response. This test, (II-5) and the comparable dc test (I-2) are similarly directed. We expect the results of these tests also to be similar, and hopefully to be so much so that one or the other may be deleted from the schedule.

Finally, a series of tests are proposed to evaluate the necessity for a reliable heat sink to insure protection against the hazard of cook-off.

#### 1.2 Outline of HERO Tests for the Modified MK 7 Ignition Element

The modification of the MK 7 ignition element was designed by Franklin Institute and produced by Atlas Chemical Industries. As part of this development program a number of acceptance tests, including RF sensitivity, were performed. This development and evaluation of this item are documented in a final report. Since most of these tests are included in the general HERO Test Program just described, there is no need for their being repeated. Consequently the test schedule shown in Table 1-2 will be used for this item.

There are approximately 800 elements remaining in the lot first made by Atlas. The test schedule calls for expending 640. Because of the changes in RF firing equipment and procedures that may have occurred in the interim it may be necessary to repeat a few earlier tests, which would use up the other 160 items.

<sup>\*</sup>Franklin Institute Lab. Final Technical Report F-B1836, "RF Protection of MARK 2 MOD 0 and MARK 7 MOD 0 Ignition Elements" by David W. Mayer and Paul F. Mohrbach, April 25, 1961 to February 23, 1962, Contract No. DA-36-034-501-ORD-3431RD.

P-B1980-2

Table 1-2

## TEST PROGRAM FOR THE MODIFIED MK 7 IGNITION ELEMENT

	Tes	<u>t</u>	No. of Items
I.	DC	Sensitivity	
	1.	DC Sensitivity Curve (Two points already determined - 1 msec and 10 sec) Determine one point at 0.1 msec or less.	50
	2.	Determine the alteration in sensitivity resulting from exposure to (say) 0.1% firing current for 5 minutes.	100
	3.	Determine dr/dt for 0.1 msec or less,1 msec and 10 sec pulses.	30
II.	RF	Sensitivity	
	1.	Determine RF sensitivity at 30 Mc, 200 Mc, and 5000 Mc with CW (10 Mc, 400 Mc and 900 Mc already determined).	150
	2.	Calculate RF sensitivity under pulsed conditions from dc data and check at 2 pulse lengths and repetition rates.	100
	3.	Determine RF sensitivity at 10 Mc, 30 Mc, 200 Mc, 400 Mc, 900 Mc, and 5000 Mc using instrumented units.	10
	4.	Expose 50 items each to 0.1% level CW and 0.1% level at 1 $\mu$ sec (pulsed RF) for 5 minutes, each at a selected frequency. Fire items subsequently in a dc Bruceton to check for dudding and alteration of sensitivity.	100
III.	Cookoff Sensitivity		
	1.	Determine cookoff sensitivity for EED in an air environment with 3 kMc both lead-to-lead and lead-to-case-CW.	50

P-B1980-2

2. Determine cookoff sensitivity for EED in a heat sink with 3 kMc both lead-to-lead and lead-to-case-CW (heat sink to be agreed upon later).

\_<u>50</u> 640 Total

#### 2. COMPONENT DEVELOPMENT

Work on this phase of the program has been completely haited awaiting further instructions from the Naval Weapons Laboratory, except for correcting an error in the die parts for the MK 1 half-plug assembly. The compression pin designed to form the mating surface (flat surface with lead grooves) was originally made with the grooves separated by 0.060 inch center to center. For the MK 1 MOD 0 squib the lead separation is 0.060 inch clear space (approximately .086 center to center). A new compression pin to form the correct mating surface has been designed and constructed.

#### 3. INSTRUMENTATION

3.1 Improved RF Attenuating Measuring Systems

The precision carriages, basic to the new system, are still in development, but final assembly is in process. Early during the next period these tuner adjusting assemblies should be in operation, and the complete system will be checked out. This development, therefore, should be concluded during the next period.

3.2 RF Power Measuring Techniques; Consideration of Errors
Associated with Differential Power Detection

Methods for measuring by power differential depend upon comparing signals representing incident and reflected powers, whose difference should correspond to net power absorbed by the components terminating the power-sampling section of the system. A pair of directional couplers (or a dual directional coupler) is the heart of the differential power

P-B1980-2

detection system. Analysis of this unit has shown that results can be inordinately in error unless means are taken to reduce, if not eliminate, their cause. The following sections detail the error analysis; the first steps toward their circumvention will follow in the next period.

#### 3.2.1 Incident Power Error

Consider a directional coupler oriented in a transmission line to sample the incident power as shown in Figure 3-1. The line is terminated in an arbitrary impedance so that both incident and reflected powers, P<sup>+</sup> and P<sup>-</sup> respectively, are present. The magnitude of the incident and reflected voltages are related to these powers by


$$V^{+} = \sqrt{P^{+}R_{o}} \qquad \text{(volt)}$$

$$V^{-} = \sqrt{P^{-}R_{o}} \qquad \text{(volt)}$$

where R $_{_{\rm O}}$  is the characteristic impedance of the transmission line. The reflected voltage is a function of the magnitudes of the incident voltage and the reflection coefficient ( $\rho_{_{\rm P}}$ ) of the arbitrary termination.

$$V^{-} = {\rho \choose \ell} V^{+} \qquad (volt) \qquad (2)$$

Each of the main line waves is coupled into the auxiliary line; but, because of the directional characteristics of the coupler, the coupled incident wave, V<sub>1</sub>, flows toward the auxiliary port and the coupled reflected wave, V<sub>r</sub>, flows toward the matched termination where it is absorbed. Since the coupling factor between primary and auxiliary lines is the same for both waves we shall for simplicity assume it to be unity. \*NOTE: In all of the equations of this development the symbols V & p represent magnitudes, normally written as |V| & |p|. Since the magnitude and not the phasor quantity is used throughout we have eliminated magnitude signs.



P-B1980-2

The incident and reflected waves in the auxiliary transmission line will be related as are the primary line waves as stated in equation (2).

$$V_{\mathbf{r}} = \rho_{\mathbf{l}} V_{\mathbf{i}} \tag{3}$$

When a directional coupler is constructed it is impossible to make it totally perfect so that the incident wave  $(V_i)$  flows only toward the auxiliary port and the reflected wave  $(V_i)$  only toward the dissipative load. Some part of the incident wave  $(V_i)$  will flow toward the matched load, where it too will be dissipated. Likewise part of the reflected wave  $(V_i)$  will flow toward the auxiliary port where it will combine with  $(V_i)$ . A quantity expressing relationship between the undesired and the desired wave is called the directivity (D) and is given by the following expression.

$$D = 10 \log \left(\frac{P_i}{P_i'}\right) = 10 \log \left(\frac{P_r}{P_r'}\right) \qquad (db)$$

In terms of voltage this can be stated as

$$D = 20 \log \left(\frac{V_i}{V_i^!}\right) = 20 \log \left(\frac{V_r}{V_r^!}\right) \qquad (db)$$

For this discussion, it is convenient to define a quantity  $\rho_{\mbox{\scriptsize d}}$  which is related to the directivity by

$$\rho_{\mathbf{d}} = \frac{\mathbf{V}_{\mathbf{i}}^{\prime}}{\mathbf{V}_{\mathbf{i}}} = \frac{\mathbf{V}_{\mathbf{r}}^{\prime}}{\mathbf{V}_{\mathbf{r}}} = \frac{1}{\log^{-1}\left(\frac{\mathbf{D}}{20}\right)}$$
 (6)

The voltage measured at the auxiliary port is the sum of the desired voltage,  $V_i$  and the undesired voltage  $V_r'$ . A maximum error occurs when these voltages add either in or out of phase.

$$V_m = V_1 + V_r$$
 (volt) (7)

P-B1980-2

 $(V_r)$  can be expressed in terms of  $(V_r)$  using equation (6).

$$V_r' = \rho_d V_r \qquad (volt)$$

Combining with equation (3) we have

$$V_{\mathbf{r}}' = \rho_{\mathbf{d}} \rho_{\ell} V_{\mathbf{i}}$$
 (9)

and equation (7) becomes

$$V_{m} = V_{i} \quad (1 - \rho_{d} \rho_{\ell}) \quad (volt)$$
 (10)

The error associated with the power measured at the auxiliary port can be written as

$$% \text{ error} = \frac{P_{m} - P_{i}}{P_{i}} = \frac{V_{m}^{2} - V_{i}^{2}}{\frac{2}{1}}$$
 (11)

where  $P_{m}$  is the quantity actually measured and  $P_{i}$  is the true value. Combining equations (10) and (11) we have

% error = 100 
$$\cdot \frac{V_{i}^{2}(\frac{1+\rho_{d}}{\rho_{\ell}})^{2}-V_{i}^{2}}{V_{i}^{2}}$$
 (12)

which reduces to

% error = 100 · 
$$\rho_d \rho_l (\rho_d \rho_l \pm 2)$$
 (13)

Plots of this equation for several values of directivity are shown in Figure 3-2. The voltage standing wave ratio, S, is related to the magnitude of  $\rho_{\ell}$  by

$$S = \frac{L \log_{\ell}}{1 - c_{\ell}} \tag{14}$$

THE FRANKLIN INSTITUTE • Laboratories for Research and Development

P-B1980-2




FIG. 3-2. MAXIMUM MEASUREMENT ERROR DUE TO DIRECTIONAL COUPLER DIRECTIVITY

P-B1980-2

The curves show that the error produced by the finite directivity of a coupler increases to a maximum value as the reflection coefficient approaches unity. For 40 db of directivity the maximum error for large reflection coefficients approaches 2%.

#### 3.2.2 Reflected Power Error

Consider another coupler connected to the same transmission line but oriented to measure the reflected power as shown in Figure 3-1. In respect to the primary line waves, the auxiliary line incident wave is directed to the auxiliary termination and the reflected wave is directed to the auxiliary port. We will assume both couplers to have the same coupling factor (unity) and directivity. Equations (3) and (6) then, also apply for the reflected power coupler.

The measured voltage at the auxiliary port is again the sum of the desired and undesired voltages, and for maximum error they are added either in or out of phase.

$$V_{m} = V_{r} \pm V_{i}$$
 (volt) (15)

From Equation (6)  $V_i$  can be expressed in terms of  $V_i$ .

$$V_{i} = \rho_{d} V_{i} \qquad (volt)$$

Substituting from Equation (3) gives us

$$v_{\perp} = \frac{\rho_{\rm d}}{\rho_{\rm l}} \quad V_{\rm r} \qquad (volt) \tag{17}$$

Combining equation (15) and (17)

$$V_{m} = V_{r} \quad 1 \pm \frac{\rho_{d}}{\rho_{\ell}} \qquad (volt)$$
 (18)

P-B1980-2

The error associated with the power measured at the auxiliary port is

$$\% \text{ error} = 100 \cdot \frac{V_r^2 \left(1 \pm \frac{\rho_d}{\rho_\ell}\right)^2 - V_r^2}{V_r^2}$$
(19)

which reduces to

$$% \text{ error} = 100 \cdot \frac{\rho_d}{\rho_\ell} \left( \frac{\rho_d}{\rho_\ell} \pm 2 \right)$$
 (20)

This equation is plotted as a family of curves for various directivities in Figure 3-2. Here the error approaches infinity for small reflection coefficients but decreases to the same value as the incident power error for large reflection coefficients (both couplers having the same directivity).

The large error which develops when measuring power reflected from a termination whose reflection coefficient is small can be explained as follows: The magnitude of the reflected power decreases with a decrease in the termination's reflection coefficient while the directivity error signal, which is proportional to the incident power, remains approximately constant. The percent error must, therefore, increase. When measuring the incident power, however, the directivity error signal is proportional to the reflected power, which decreases with decreasing reflection coefficient, the percent error likewise decreases.

#### 3.2.3 New Power Error

The net power flow in a transmission line is the difference between the incident and reflected powers. The maximum error of the new power is, therefore,

% error = 100 
$$\frac{(P_{mi} - P_{mr}) - (P_{i} - P_{r})}{(P_{i} - P_{r})}$$
 (21)

P-B1980-2

Substituting square of the voltages measured at the auxiliary ports as given in Equations (10), and (18) we have

% error = 100 
$$\frac{V_{i}^{2} \left(1 \pm \rho_{d} \rho_{\ell}\right)^{2} - V_{r}^{2} \left(1 \pm \frac{\rho_{d}}{\rho_{\ell}}\right)^{2} - V_{i}^{2} + V_{r}^{2}}{V_{i}^{2} - V_{r}^{2}}$$
(22)

substituting  $V_r = \rho_\ell V_i$  as given in equation (3) and expanding we have

$$\% \text{ error} = 100 \left[ \frac{\pm \rho_{\mathbf{d}} \rho_{\ell}}{1 - \rho_{\ell}^{2}} - \rho_{\mathbf{d}}^{2} \right]$$
 (23)

The final equation for the percent error associated with the differential power is also plotted as a family of curves for various values of directivity. This error is very small for small reflection coefficients but increases rapidly as the coefficient approaches unity.

In light of the fact that both incident and reflected power errors approach a common value (both in percent and in magnitude) when the reflection coefficient approached unity it may seem surprising that the net power error becomes increasingly larger. The problem here is that the net power error is the sum of the magnitudes of the incident and reflected errors, and it too approaches a fixed value as the reflection coefficient approaches unity, while the net power, on the other hand, becomes smaller and smaller, approaching zero. The magnitude of the error can in fact be several times greater than the magnitude of the net power for a reflection coefficient sufficiently close to unity. Unfortunately, most electroexplosive devices have rather high reflection coefficients when used as the termination of a transmission line. For example, a device with a nominal reflection coefficient of 0.82, which is equivalent to a purely resistive load of 5 ohms, will produce a possible error of ± 10% when using two 40 db directivity directional couplers to measure net power. Further steps must be taken to reduce the net power error if this type of measurement is to be practical.

P-B1.980-2

One such step is a reduction in the directivity error through phase shifting techniques. We assumed in our development of the incident and reflected power errors that the greatest error will occur when the desired and undesired voltages add either in or out of phase at the coupler auxiliary ports. The actual phase relationship between these waves is dependent on the phase relationship of the incident and reflected waves in the primary transmission line. It may be possible, through shifting the relative phase of these waves to produce maximum and minimum measurements, whose average should be the actual value (for large reflection coefficients the positive and the negative errors are approximately equal). More investigation is needed, however, before we can apply this technique.

#### **ACKNOWLEDGEMENTS**

Significant contributions to Section 3 of this report were made by George McKay. The contributions of Peter Altman of NWL speaking for his associates and of Robert F. Wood to the substance of Section 1 are also acknowledged.

Paul F. Mohrbach Group Leader

Norman P. Faunce Project Leader

Approved by:

E. E. Hannum, Manager Applied Physics Laboratory

P-B1980-2

#### DISTRIBUTION LIST

Chief, Naval Operations (OP-411H) Commanding Officer Department of the Navy U.S. Naval Air Development Center Washington 25, D. C. Johnsville, Pennsylvania Code: EL 94 Chief, Bureau of Naval Weapons Department of the Navy Officer-in-Charge Washington 25, D. C. U.S. Naval Explosive Ordnance Disposal Code: C-132 Technical Center RAAV-3421 U.S. Naval Propellant Plant RM-15 Indian Head, Maryland RMMO-224 RMMO-235 Commanding Officer RMMO-32 U.S. Naval Underwater Ordnance Station RMMO-33 Newport, Rhode Island RMMO-4 RMM0-43 Director RMMO-44 U.S. Naval Research Laboratory RMMP-343 Washington 25, D. C. RREN-32 Code: 5410 (2) DIS-313 (4) Commandant of the Marine Corps Chief, Bureau of Yards and Docks Washington 25, D. C. Department of the Navy Code: AO4C Washington 25, D. C. Attn: Code D-200 Commander Pacific Missile Range P. O. Box 8 Commander U.S. Naval Ordnance Laboratory Point Mugu, California White Oak, Maryland Att: Code 3260 Code: ED NO Commanding Officer and Director U.S. Navy Electronics Laboratory Technical Library San Diego 52, California Att: Library Commanding Officer U.S. Naval Ordnance Laboratory Commanding Officer Corona, California Attn: Code 561 U.S. Naval Ammunition Depot Crane, Indiana Code: 34 Commander U.S. Naval Ordnance Test Station Commanding Officer China Lake, California U.S. Naval Ordnance Plant Code: 556 Macon, Georgia 4572 Attn: Code PD 270

### DISTRIBUTION LIST (Continued)

Commander Naval Air Force U.S. Atlantic Fleet (CNAL 724B) U.S. Naval Air Station Norfolk 11, Virginia

Commander Training Command U.S. Pacific Fleet c/o U.S. Fleet Anti-Submarine Warfare School San Diego 47, California

Commanding General Headquarters, Fleet Marine Force, Pacific c/o Fleet Post Office San Francisco, California Attn: Force Communications Electronic Officer

Commander in Chief U.S. Pacific Fleet c/o Fleet Post Office San Francisco, California Attn: Code 4

Commander Seventh Fleet c/o Fleet Post Office San Francisco, California

Commander
New York Naval Shipyard
Weapons Division,
Naval Base
Brooklyn 1, New York
Attn: Code 290

Commander
Pearl Harbor Naval Shipyard
Navy No. 128, Fleet Post Office
San Francisco, California
Attn: Code 280

Commander
Portsmouth Naval Shipyard
Portsmouth, New Hampshire

Department of the Army
Office Chief of Ordnance
Washington 25, D. C.
Attn: ORDGU-SA
ORDTN
ORDTB (Research & Special
Projects)

Office Chief Signal Officer Research and Development Division Washington 25, D. C. Attn: SIGRD-8

Commanding Officer
Diamond Ordnance Fuze Laboratories
Washington 25, D. C.
Attn: Mr. T. B. Godfrey

U.S. Army Nuclear Weapon Coordination Group Fort Belvoir, Virginia

Director
U.S. Army Engineer Research and
Development Labs.
Fort Belvoir, Virginia
Attn: Chief, Basic Research Group

Commanding Officer
Picatinny Arsenal
Dover, New Jersey
Attn: Artillery Ammunition &
Rocket Development Laboratory Mr. S. M. Adelman
Attn: Evaluation Unit, Instrumentation
Section, Building 352 - Mr. Abraham
Grinoch,

Commanding General Headquarters 2DRAADCOM Fort George G. Meade, Maryland Attn: Radar Officer

Commanding Officer
U.S. Army Signal Research & Development
Lab.
Fort Monmouth, New Jersey
Attn: SIGEM/EL-GF

P-B1980-2

## DISTRIBUTION LIST (Continued)

Commander
U.S. Army Ordnance
Frankford Arsenal
Philadelphia 37, Pennsylvania

Commander
U.S. Army Rocket & Guided Missile
Agency
Redstone Arsenal, Alabama
Attn: ORDXR-R (Plans)

Commanding Officer
Office of Ordnance Research,
U.S. Army
Box CM, Duke Station
Durham, North Carolina
Attn: Internal Research Division

Commanding General White Sands Missile Range New Mexico Attn: ORDBS-G3

Commanding Officer
White Sands Missile Range, New Mexico
U.S.A. SMSA
Attn: SIGWS-AJ

Commanding General U.S. Army Electronic Proving Ground Ft. Huachuca, Arizona

Director of Office of Special Weapons
Developments
United States Continental Army Command
Fort Bliss, Texas
Attn: Capt. Chester I. Peterson
T S Control Officer

Headquarters
Air Research and Development Command
Andrews Air Force Base
Washington 25, D.C.
Attn: RDMMS-3

Commander
Air Force Missile Test Center
Patrick Air Force Base, Florida
Attn: Code MTRCF2

Director Nuclear Safety Kirtland AFB, N.M. Research Attn: AFCNS

Headquarters
Ogden Air Material Area
Hill Air Force Base
Ogden, Utah
Code OOYSS

Commander
Air Force Missile Development Center
Holloman Air Force Base
Alamagordo, New Mexico

Griffiss AF Base RADC, New York Attn: RCLS/Philip L. Sandler

Commander
Air Force Special Weapons Center
Kirtland Air Force Base
Albuquerque, New Mexico
Attn: SWVSA

Director of Missile Safety Research Deputy IG for Safety Norton AFB, California

Commanding General Air Fleet Marine Force, Pacific MCAS, El Toro Santa Ana, California

Strategic Air Command Offutt Air Force Base, Nebraska Attn: DOSDM

P-B1980-2

# DISTRIBUTION LIST (Continued)

Commander
Headquarters Ground Electronics
Engineering Installation Agency
Griffiss Air Force Base
Rome, New York
Code ROZMWT

Armed Services Explosives Safety Board Department of Defense Room 2075, Gravelly Point, Bldg. T-7 Washington 25, D. C.

Headquarters
Armed Services Technical Information
Agency (TIPCR)
Arlington Hall Station
Arlington 12, Virginia
Via: U.S. Naval Weapons Laboratory
Dahlgren, Virginia (10)

Commander
Field Command
Defense Atomic Support Agency
Albuquerque, New Mexico
Attn: FCDR3

U.S. Atomic Energy Commission Division of Military Application Washington 25, D. C.

Defense Research Staff
British Embassy
3100 Mass. Ave., N.W.
Washington 8, D. C.
Attn: Mr. G. R. Nice
Via: U.S. Naval Weapons Laboratory
Dahlgren, Virginia

Naval Member
Canadian Joint Staff
2450 Massachusetts Ave., N.W.
Washington 8, D. C.
Attn: Staff Officer (Weapons)
Via: U.S. Naval Weapons Laboratory
Dahlgren, Virginia

American Machine and Foundry Co.-Alexandria Div. 1025 North Royal Street Alexandria, Virginia Attn: Dr. L. F. Dytrt (Contract AF-29(601)-2769)

Atlas Powder Company Reynolds Ordnance Section P. O. Box 271 Tamaqua, Pennsylvania Attn: Mr. R. Mc Girr

The Bendix Corp. Scintilla Div. Sidney, N. Y. Attn: R. M. Purdy

Bermite Powder Company 22116 West Soledad Canyon Road Saugus, California Attn: Mr. L. LoFiego

Chance Vaught Corp. P. O. Box 5907 CH#1 Dallas 22, Texas Attn: R. D. Henry

Aerojet-General Corporation P. O. Box 296 Azusa, California Attn: Myra Z. Grenier, Librarian

Gruman Aircraft Engineering Corporation Weapons Systems Department Bethpage, Long Island, New York Attn: Mr. E. J. Bonan

Hanscom Air Force Base, Massachusetts Codes: AFCCDD/CCSEI-1 Attn: Capt. Long

### DISTRIBUTION LIST (Continued)

Jansky & Bailey, Inc. 1339 Wisconsin Ave., N.W. Washington, D. C. AttN: Mr. F. T. Mitchell, Jr. Contract N178-7604

Lockheed Aircraft Corporation P. O. Box 504 Sunnyvale, California

Attn: Missile Systems Division, Dept. 62-20 Mr. I. B. Gluckman

Attn: Missiles and Space Division, Dept.Communication Services

81-62 Mr. E. W. Tice Attn: Missiles and Space Division, Dept.Columbus 16, Ohio

81-71 Mr. R. A. Fuhrman

McCormick Selph Associates Attn: Technical Librarian Hollister, California

Midwest Research Institute 425 Volker Boulevard Kansas City, Missouri Attn: Security Officer

RCA Service Company Systems Engineering Facility Government Service Department 838 N. Henry Street Alexandria, Virginia Attn: Mr. C. M. Fisher

Sandia Corporation (Division 1262) Albuquerque, New Mexico Via: FCDASA

University of Denver Denver Research Institute Denver 10, Colorado Attn: Mr. R. B. Feagin

U.S. Flare Division Atlantic Research Corp. 19701 W. Goodvale Road Saugus, California Attn: Mr. N.E.Eckert, Head, R & D Group

Vitro Laboratories 14000 Georgia Avenue Silver Spring, Maryland Attn: Miss C. M. Jaques, Librarian

Welex Electronics Corporation Solar Building, Suite 201 16th and K Streets, N. W. Washington 5, D. C.

North American Aviation, Inc.

4300 E. 5th Ave.

U. S. Naval Weapons Laboratory Dahlgren, Virginia Attn: Code WHR (2)